CONTRACT CHAI	NGE ORDE	R MEN	IORANDUM				DATE:	9/22/2011	Page 1 of 1	
TO: Tony Anziano, Program Manager / FROM: Kannu Balan, Senior TE					E.A.	04 - 0120F4				
					- CO-RTE-PM SF-80-13.2/13.9 FED. NO.					
CCO#: 192 SUPPL	EMENT#: 0	0 Category Code: CBPC			CONTINGENCY BALANCE (incl. this change)			e) \$146,593,888.11		
COST: \$467,978.00 INCREASE ☑ DECREASE □				HEADQUARTERS APPROVAL REQUIRED? ✓ YES ☐ NO						
SUPPLEMENTAL FUNDS PROVIDED: \$0.00					IS THIS REQUEST IN ACCORDANCE WITH ✓ YES NO ENVIRONMENTAL DOCUMENTS?					
CCO DESCRIPTION: OTD Divider Rail Light Housing					PROJECT DESCRIPTION: CONSTRUCT SELF-ANCHORED SUSPENSION BRIDGE					
Original Contract Time: Time Adj. This Change: Previously Approved CC Time Adjustments:				со		ntage Time Adjusted: ing this change)		Total # of Unreconciled Deferred Time CCO(s): (including this change)		

DATE: 0/00/0044

3

THIS CHANGE ORDER PROVIDES FOR:

Day(s)

2490 Day(s)

Modifying the light housing for the fixtures in the completed bikepath railing divider sections and installing cover plates for the existing wiring hand holes on the Oakland Touchdown (OTD) portion of the San Francisco/Oakland Bay Bridge (SFOBB) East Span Seismic Safety Project. Removing and replacing all bolts, dielectric material, and bolt caps at all the rail base plates, and adjust shims as required to maintain the existing top of rail profile of the OTD North and South bikepath railings. New steel will be galvanized and painted during fabrication except for field finish painting which will be painted in a future change order.

Day(s)

501

20 %

The light housing fixtures and grills for the OTD bikepath divider rails are being revised to match the fixtures on the Skyway bikepath divider rails. The fixtures on the OTD bikepath differ in that the grill spacing is different in appearance than those on the Skyway. This change order will correct the length differences of the lighting fixtures and maintain a consistent aesthetic appearance throughout the corridor. This change will also have an additional benefit of simplifying future maintenance work in that they will have only one type of divider rail fixture to maintain. Wiring hand hole cover plates were not installed under the OTD Contract. The anchor bolts are loose, the dielectric material is deteriorating, and the bolt caps also are different from those on the Skyway.

The total cost of this change order is \$467,978.00, which can be financed from the contingency fund. A detailed cost analysis is on file.

No time adjustment is warranted as this change order does not affect the controlling operation.

This change order has concurrence from Peter Siegenthaler (Principal TE), William Casey (Supervising TE), Rich Foley (HQ Oversight), Ken Terpstra (Proj. Manager), Wenyi Long (Design Oversight), Lina Ellis (Maintenance), and Jing Chen (District Design) April 6, 2011

Design) April 6, 20	11.							
CONCURRED BY:			ESTIMATE OF COST					
Construction Engineer:	PCE, Pete Siegenthaler, Prin TE	Date 5/10/11			THIS REQUEST	TOTAL TO DATE		
Bridge Engineer:	William Casey, Sup TE	Date	5/4/11	ITEMS	\$0.00	\$0.00		
- Dridgo Eriginoon	William Gasey, Gap 12	Duto	0/7/11	FORCE ACCOUNT	\$0.00	\$0.00		
Project Engineer:	CT Oversight, Wenyi Long, P.E.	Date	4/6/11	AGREED PRICE	\$467,978.00	\$467,978.00		
Project Manager:	Proj Manager, Ken Terpstra	Date	9/22/11	ADJUSTMENT	\$0.00	\$0.00		
FHWA Rep.:		Date		TOTAL	\$467,978.00	\$467,978.00		
Environmental:		Date			FEDERAL PARTICIPATION			
Liiviioiiiieiitai.		Date		PARTICIPATING	PARTICIPATING IN PA	ART NONE		
Other (specify):	HQ, Rich Foley	Date	5/10/11	NON-PARTICIPATIN		NON-PARTICIPATING		
Other (specify):	Struct. Maint, Lina Ellis	Date	4/5/11	FEDERAL SEGREGATION		Source or PTP type)		
District Prior Approval By:		Date		CCO FUNDED PER CONTRACT CCO FUNDED AS FOLLOWS				
HQ (Issue Approve) By:		Date		FEDERAL FUNDING S	PERCENT			
Resident Engineer's Signature:		Date						
Dam Bale		9-22-11		<i>≟</i> ·				